

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 2

PATENT NO. : 6,856,597 B1

APPLICATION NO.: 09/780,775

ISSUE DATE : February 15, 2005

INVENTOR(S) : Bob Scott

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In FIGS. 2, 3, and 8, the Signal Front End System reference numeral "32" should read --28--.

In FIG 2, the Power Budgeter Unit reference numeral "62" should read --61--.

In FIG. 7, the reference numeral "128" should read --218--.

In FIG 8, the Transceiver reference numeral "222" should read --252-- and the Memory reference numeral "226" should read --256--.

In column 2, line 29: the text "central office (CO) 22 coupled" should read --central office (CO) 22 is coupled--.

In column 6, line 62 and column 7, lines 7, 12, 19, 54, 57: the reference numeral "62" should read --61--.

In column 7, line 12: the text "multiple transceiver unit 62" should read --multiple transceiver unit 64--.

In column 8, lines 1, 6, 9: the reference numeral "60" should read --90--.

In column 8, line 3 and column 18, lines 41, 50, 53, 54-55: the text "PB processor 90" should read --PB processor 92--.

In column 8, line 22: the text "front end system 32" should read --front end system 28--.

In column 10, line 37: the reference numerals "124-126" should read --124-146--.

In column 12, line 41: the text "transceiver port cards 66" should read --transceiver port card 66--.

In column 12, line 49: the text "six symbol periods are shown" should read --six symbol periods 148-158 (and 172-182 of FIG. 6) are shown--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

THOMAS, KAYDEN, HORSTEMEYER & RISLEY, L.L.P.
 600 Galleria Parkway, Suite 1500
 Atlanta, Georgia 30339

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 2 of 2

PATENT NO. : 6,856,597 B1

APPLICATION NO.: 09/780,775

ISSUE DATE : February 15, 2005

INVENTOR(S) : Bob Scott

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 12, line 56: the text "period (162, 166, 170). A customer" should read --period (162, 166, 170) while symbol periods 160, 164, and 168 are active. A customer--.

In column 14, lines 24 and 32: the reference numeral "69" should read --96--.

In column 15, lines 63-64: the text "The process starts at block 212" should read --The process starts at block 202--.

In column 15, line 66: the text "shown in block 202" should read --shown in block 204--.

In column 8, line 66; column 9, lines 1-3, 23, 25-26; column 18, lines 24, 32-33, 36; and column 19, line 63: the text "multiple transceiver unit 66" should read --multiple transceiver unit 62--.

In column 19, lines 16 and 26: the text "transmitter 268" should read --transmitter 258--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

THOMAS, KAYDEN, HORSTEMEYER & RISLEY, L.L.P.
600 Galleria Parkway, Suite 1500
Atlanta, Georgia 30339

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.